

Performance Charts

MACHINE NO.	PSIG	GPM								CYCLE TIME								
		<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>	<u>E</u>	<u>F</u>	<u>G</u>	<u>H</u>	<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>	<u>E</u>	<u>F</u>	<u>G</u>	<u>H</u>	
		1/4"	9/32"	5/16"	3/8"	7/16"	1/2"	9/16"	5/8"	1/4"	9/32"	5/16"	3/8"	7/16"	1/2"	9/16"	5/8"	
360-2S-200-X11-V1	40		31	36	51	66	80	94	103			97	50	23	14	10	8	7
360-2S-200-X11-V1	60	32	39	47	63	83	101	118	135	113	53	30	16	10	8	6	5	5
360-2S-200-X11-V1	80	37	44	54	74	96	118	138	157	73	37	22	13	9	6	5	5	5
360-2S-200-X11-V1	100	41	50	60	83	105	130	151	172	55	30	19	11	7	6	5	4	4
360-2S-200-X11-V1	120	45	54	65	90	115	143	166	191	44	25	16	9	7	5	4	4	4
360-2S-200-X11-V1	140	48	57	70	98	125	155	184	212	37	21	14	8	6	5	4	3	3
360-2S-200-X13-V2	40	34	38	45	59	68	86	100	112		34	22	14	10	8	7	6	6
360-2S-200-X13-V2	60	42	48	56	73	91	110	125	140	45	21	15	10	8	6	5	5	5
360-2S-200-X13-V2	80	49	56	66	85	105	128	145	164	30	17	13	9	7	5	5	4	4
360-2S-200-X13-V2	100	54	62	71	94	117	140	163	181	25	14	11	8	6	5	4	4	4
360-2S-200-X13-V2	120	58	67	79	104	128	154	179	203	22	13	9	7	5	4	4	3	3
360-2S-200-X13-V2	140	62	72	84	111	138	169	197	223	19	11	9	6	5	4	4	3	3
360-2S-201-X11-V1	40	26	31	37	50	63	74	84	91		28	20	13	10	8	7	6	6
360-2S-201-X11-V1	60	32	39	47	62	78	94	106	114	100	20	14	9	7	6	5	4	4
360-2S-201-X11-V1	80	38	46	53	72	91	108	123	135	53	16	12	8	6	5	4	4	4
360-2S-201-X11-V1	100	42	50	60	81	100	121	134	149	40	14	10	7	5	4	4	3	3
360-2S-201-X11-V1	120	45	54	65	88	110	132	149	163	30	12	9	6	5	4	3	3	3
360-2S-201-X11-V1	140	48	57	69	95	119	142	164	182	25	11	8	6	4	4	3	3	3
360-2S-201-X13-V2	40	34	37	44	55	66	80	87	96		18	14	10	8	6	6	5	5
360-2S-201-X13-V2	60	41	47	56	70	84	100	108	121	31	13	10	7	6	5	4	4	4
360-2S-201-X13-V2	80	47	55	64	79	97	115	129	142	24	11	9	6	5	4	4	4	4
360-2S-201-X13-V2	100	53	61	70	90	110	130	144	157	20	9	8	5	4	4	4	3	3
360-2S-201-X13-V2	120	57	66	77	99	120	140	159	173	16	8	7	5	4	4	3	3	3
360-2S-201-X13-V2	140	62	69	83	106	130	155	175	193	14	7	6	5	4	3	3	3	3
360-2S-203-X11-V1	40		31	36	51	65	82	95	106		95	54	28	19	15	12	10	10
360-2S-203-X11-V1	60		38	46	64	83	101	119	135		53	34	20	14	11	9	8	8
360-2S-203-X11-V1	80		45	54	75	95	119	138	157		39	26	16	12	9	7	6	6
360-2S-203-X11-V1	100		50	60	83	106	132	152	174		32	22	14	10	8	7	6	6
360-2S-203-X11-V1	120		53	65	90	116	142	167	192		27	19	12	9	7	6	5	5
360-2S-203-X11-V1	140		57	70	97	125	157	187	215		24	17	11	8	7	5	5	5
360-2S-203-X13-V2	40	34	39	44	58	73	89	103	114		82	40	20	14	11	9	8	8
360-2S-203-X13-V2	60	41	49	56	73	93	110	127	145	65	38	24	14	11	8	7	6	6
360-2S-203-X13-V2	80	48	56	66	85	107	127	148	168	42	27	18	12	9	7	6	6	6
360-2S-203-X13-V2	100	54	62	72	95	119	143	165	187	35	22	16	10	8	6	5	5	5
360-2S-203-X13-V2	120	58	67	79	103	131	156	182	206	30	19	14	9	7	6	5	4	4
360-2S-203-X13-V2	140	62	72	84	113	140	173	202	229	25	17	12	8	7	5	5	4	4
360-2S-600-X11-V1	40			36	48	64	79	94	98			91	51	35	26	20	18	18
360-2S-600-X11-V1	60	30	37	44	62	80	99	113	128		112	65	36	26	20	16	14	14
360-2S-600-X11-V1	80	34	42	51	71	93	114	132	152	152	76	49	30	21	16	13	12	12
360-2S-600-X11-V1	100	39	47	58	79	104	127	147	170	112	62	42	26	18	14	12	10	10
360-2S-600-X11-V1	120	41	51	63	86	113	141	158	184	96	54	36	23	17	13	11	9	9
360-2S-600-X11-V1	140	44	55	67	93	121	152	182	205	79	51	32	20	15	12	10	8	8
360-2S-600-X13-V2	40		37	43	53	71	87	98	111		60	47	32	24	19	18	15	15

Performance Charts

MACHINE NO.	PSIG	← GPM →								← CYCLE TIME →							
		<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>	<u>E</u>	<u>F</u>	<u>G</u>	<u>H</u>	<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>	<u>E</u>	<u>F</u>	<u>G</u>	<u>H</u>
		1/4"	9/32"	5/16"	3/8"	7/16"	1/2"	9/16"	5/8"	1/4"	9/32"	5/16"	3/8"	7/16"	1/2"	9/16"	5/8"
360-2S-600-X13-V2	60	39	45	53	70	88	109	123	138	61	46	36	25	19	16	14	12
360-2S-600-X13-V2	80	45	53	62	83	101	124	144	163	49	37	30	21	17	14	12	11
360-2S-600-X13-V2	100	49	58	70	90	113	138	159	179	42	33	27	19	15	12	11	9
360-2S-600-X13-V2	120	54	63	76	98	125	153	174	198	38	29	24	17	13	11	10	8
360-2S-600-X13-V2	140	58	68	81	106	135	167	194	220	34	27	22	16	12	10	9	8
360-2S-601-X11-V1	40		29	35	47	60	73	82	91		63	52	34	24	20	16	15
360-2S-601-X11-V1	60	31	36	43	60	76	92	104	115	84	50	37	25	18	15	13	11
360-2S-601-X11-V1	80	35	42	52	69	88	106	123	134	58	41	30	20	15	12	11	9
360-2S-601-X11-V1	100	39	47	57	77	98	118	134	148	49	35	27	18	13	11	10	8
360-2S-601-X11-V1	120	42	51	61	85	107	130	148	163	44	32	24	16	12	10	9	8
360-2S-601-X11-V1	140	45	54	67	91	117	140	163	181	39	29	21	15	11	9	8	7
360-2S-601-X13-V2	40	32	37	42	54	66	76	83	94		41	34	25	20	17	15	14
360-2S-601-X13-V2	60	39	45	52	68	81	98	109	118	39	31	26	19	16	14	12	12
360-2S-601-X13-V2	80	45	52	60	78	96	114	126	138	32	26	23	17	13	12	10	10
360-2S-601-X13-V2	100	50	58	68	87	106	124	139	153	28	23	20	15	12	10	9	9
360-2S-601-X13-V2	120	54	63	74	95	116	138	154	169	26	21	18	14	11	9	8	8
360-2S-601-X13-V2	140	59	67	78	103	126	150	171	188	24	20	17	13	10	9	8	7
360-2S-603-X11-V1	40		28	35	49	63	80	94	106		188	136	81	54	42	34	31
360-2S-603-X11-V1	60		37	43	61	80	100	118	133		119	90	56	40	30	25	23
360-2S-603-X11-V1	80	35	42	52	72	94	116	136	153	142	94	73	44	32	24	20	18
360-2S-603-X11-V1	100	38	46	57	79	103	129	149	170	116	82	61	38	28	21	17	15
360-2S-603-X11-V1	120	41	51	63	87	113	142	163	188	98	73	54	33	24	19	16	13
360-2S-603-X11-V1	140	44	54	67	94	122	154	182	207	86	68	48	30	22	17	14	12
360-2S-603-X13-V2	40	33	37	43	57	72	88	101	113		90	68	45	35	28	24	21
360-2S-603-X13-V2	60	40	46	54	72	90	110	127	142	86	63	50	35	28	23	19	17
360-2S-603-X13-V2	80	46	54	63	82	104	128	147	166	67	52	42	30	23	19	16	14
360-2S-603-X13-V2	100	51	60	70	93	117	142	167	186	57	46	37	26	21	17	14	13
360-2S-603-X13-V2	120	56	65	77	102	127	156	180	204	53	42	33	24	19	15	13	11
360-2S-603-X13-V2	140	59	68	81	108	135	170	199	226	47	38	31	22	17	14	12	11
360-3S-200-X11-V1	40	37	45	54	73	89	109	122	133		26	19	12	9	7	6	5
360-3S-200-X11-V1	60	48	57	70	93	115	134	152	167	26	18	13	9	7	5	5	4
360-3S-200-X11-V1	80	56	68	81	108	132	159	177	195	20	14	11	7	6	4	4	4
360-3S-200-X11-V1	100	62	74	89	118	147	175	196	215	17	12	9	6	5	4	4	3
360-3S-200-X11-V1	120	67	80	97	130	162	193	221	241	15	11	8	6	4	4	3	3
360-3S-200-X11-V1	140	71	85	103	141	179	215	244	264	13	10	8	5	4	3	3	3
360-3S-200-X13-V2	40	43	51	60	78	96	111	125	136		17	14	10	7	6	6	5
360-3S-200-X13-V2	60	54	64	74	96	118	139	155	171	16	13	10	7	6	5	5	4
360-3S-200-X13-V2	80	63	74	85	113	137	162	183	198	13	11	9	6	5	4	4	3
360-3S-200-X13-V2	100	69	82	96	125	151	179	202	219	12	9	8	6	5	4	3	3
360-3S-200-X13-V2	120	74	89	104	136	168	199	224	246	11	9	7	5	4	4	3	3
360-3S-200-X13-V2	140	80	95	111	149	187	220	248	267	10	8	6	5	4	3	3	3
360-3S-201-X11-V1	40	37	45	53	68	83	93	102	107		15	12	8	7	6	5	5
360-3S-201-X11-V1	60	47	56	66	86	104	118	130	136	15	11	9	6	5	4	4	4

Performance Charts

MACHINE NO.	PSIG	GPM								CYCLE TIME							
		<u>A</u> 1/4"	<u>B</u> 9/32"	<u>C</u> 5/16"	<u>D</u> 3/8"	<u>E</u> 7/16"	<u>F</u> 1/2"	<u>G</u> 9/16"	<u>H</u> 5/8"	<u>A</u> 1/4"	<u>B</u> 9/32"	<u>C</u> 5/16"	<u>D</u> 3/8"	<u>E</u> 7/16"	<u>F</u> 1/2"	<u>G</u> 9/16"	<u>H</u> 5/8"
360-3S-201-X11-V1	80	55	65	76	100	121	136	148	156	11	9	7	5	4	4	4	3
360-3S-201-X11-V1	100	61	73	84	110	133	151	165	175	10	8	6	5	4	3	3	3
360-3S-201-X11-V1	120	66	79	92	121	145	167	182	193	9	7	6	4	4	3	3	3
360-3S-201-X11-V1	140	70	83	99	130	160	185	202	215	8	7	5	4	3	3	3	2
360-3S-201-X13-V2	40	43	50	56	72	85	97	104	109		12	10	7	6	5	5	5
360-3S-201-X13-V2	60	53	62	71	90	107	119	130	136	11	9	7	6	5	4	4	4
360-3S-201-X13-V2	80	62	72	83	104	124	141	152	158	9	8	6	5	4	3	3	3
360-3S-201-X13-V2	100	68	80	92	116	136	153	168	178	8	7	6	4	4	3	3	3
360-3S-201-X13-V2	120	73	87	101	126	150	169	186	196	8	6	5	4	3	3	3	3
360-3S-201-X13-V2	140	78	92	108	137	165	190	208	218	7	6	5	3	3	3	3	2
360-3S-203-X11-V1	40	38	47	56	74	93	111	127	135	81	43	29	18	13	10	9	8
360-3S-203-X11-V1	60	48	58	69	92	117	140	158	172	44	28	20	13	9	8	7	6
360-3S-203-X11-V1	80	56	68	81	108	136	162	184	198	32	22	16	10	8	6	6	5
360-3S-203-X11-V1	100	63	75	89	119	149	179	202	221	27	18	14	9	7	6	5	4
360-3S-203-X11-V1	120	67	81	97	130	165	198	225	246	24	17	12	8	6	5	5	4
360-3S-203-X11-V1	140	72	86	104	142	183	218	248	268	21	15	11	7	6	5	4	4
360-3S-203-X13-V2	40		51	60	79	98	113	128	142		39	24	15	11	9	8	7
360-3S-203-X13-V2	60	55	65	74	99	122	143	159	174	51	24	18	11	9	7	6	6
360-3S-203-X13-V2	80	64	75	88	114	141	166	185	204	31	18	14	9	7	6	5	5
360-3S-203-X13-V2	100	71	84	97	127	157	187	209	230	23	16	12	8	6	5	5	4
360-3S-203-X13-V2	120	76	90	106	140	174	207	234	255	20	14	11	7	6	5	4	4
360-3S-203-X13-V2	140	82	97	114	153	193	226	256	276	17	13	10	7	5	4	4	4
360-3S-600-X11-V1	40	39	46	54	74	91	110	122	135		62	47	29	21	16	14	13
360-3S-600-X11-V1	60	49	58	69	94	115	137	154	168	60	42	32	21	15	13	11	10
360-3S-600-X11-V1	80	57	68	81	107	134	159	182	197	45	33	26	17	13	11	9	9
360-3S-600-X11-V1	100	63	77	89	120	149	177	200	220	38	28	22	15	11	10	8	8
360-3S-600-X11-V1	120	67	81	97	131	164	196	222	244	34	26	20	14	10	8	8	7
360-3S-600-X11-V1	140	73	87	105	142	183	217	245	266	30	23	18	12	9	8	7	6
360-3S-600-X13-V2	40	45	52	61	78	97	112	123	138		37	31	22	18	15	13	12
360-3S-600-X13-V2	60	55	66	75	100	121	142	158	171	35	28	24	17	14	12	11	10
360-3S-600-X13-V2	80	65	76	88	115	139	164	184	200	29	24	20	15	12	10	9	8
360-3S-600-X13-V2	100	71	85	98	126	155	181	203	220	26	21	18	14	11	9	8	8
360-3S-600-X13-V2	120	77	90	105	139	172	202	226	245	24	20	16	12	10	8	7	7
360-3S-600-X13-V2	140	82	97	116	151	189	223	250	270	22	18	15	11	9	8	7	6
360-3S-601-X11-V1	40	38	45	52	69	82	95	102	107		37	28	20	16	13	12	12
360-3S-601-X11-V1	60	49	57	66	86	104	118	130	137	33	26	21	15	12	11	10	9
360-3S-601-X11-V1	80	56	66	77	100	120	138	150	160	27	22	17	13	10	9	8	8
360-3S-601-X11-V1	100	62	74	86	110	133	153	168	176	24	19	15	12	9	8	7	7
360-3S-601-X11-V1	120	66	80	94	122	149	169	184	195	21	17	14	10	8	7	7	6
360-3S-601-X11-V1	140	70	85	102	131	164	187	204	215	19	16	13	9	8	7	6	6
360-3S-601-X13-V2	40	43	51	58	72	86	98	105	109		26	22	17	14	12	12	11
360-3S-601-X13-V2	60	54	63	72	91	108	123	133	140	24	20	17	13	11	10	9	9
360-3S-601-X13-V2	80	63	73	85	107	125	142	154	162	21	17	14	11	10	9	8	8

Performance Charts

MACHINE NO.	PSIG	GPM								CYCLE TIME							
		<u>A</u> 1/4"	<u>B</u> 9/32"	<u>C</u> 5/16"	<u>D</u> 3/8"	<u>E</u> 7/16"	<u>F</u> 1/2"	<u>G</u> 9/16"	<u>H</u> 5/8"	<u>A</u> 1/4"	<u>B</u> 9/32"	<u>C</u> 5/16"	<u>D</u> 3/8"	<u>E</u> 7/16"	<u>F</u> 1/2"	<u>G</u> 9/16"	<u>H</u> 5/8"
360-3S-601-X13-V2	100	69	80	93	117	139	157	169	179	19	15	13	10	9	8	7	7
360-3S-601-X13-V2	120	76	88	101	128	152	173	187	200	17	14	12	9	8	7	7	6
360-3S-601-X13-V2	140	80	94	110	139	166	192	207	219	16	13	11	9	7	7	6	6
360-3S-603-X11-V1	40	39	47	55	74	93	109	127	135		109	71	42	30	25	21	19
360-3S-603-X11-V1	60	49	57	69	93	115	137	157	170		69	50	31	23	19	16	14
360-3S-603-X11-V1	80	57	68	79	108	135	161	180	199	78	53	40	26	19	16	14	12
360-3S-603-X11-V1	100	62	75	88	118	150	177	201	222	65	46	34	23	17	14	12	11
360-3S-603-X11-V1	120	67	81	96	131	163	198	225	250	58	41	30	20	15	13	11	10
360-3S-603-X11-V1	140	71	86	103	140	182	219	248	275	51	36	27	18	14	12	10	9
360-3S-603-X13-V2	40	44	52	61	81	98	115	128	141		63	48	32	25	21	18	17
360-3S-603-X13-V2	60	56	65	77	99	122	143	163	176		45	36	25	20	16	14	13
360-3S-603-X13-V2	80	64	75	89	117	143	167	189	206	50	37	30	21	17	14	12	11
360-3S-603-X13-V2	100	71	85	99	128	159	187	210	232	44	33	26	19	15	12	11	10
360-3S-603-X13-V2	120	76	91	108	141	173	207	234	257	39	30	24	17	14	11	10	9
360-3S-603-X13-V2	140	82	97	116	153	195	229	257	277	35	27	21	16	12	10	9	9